



**Note: The quantity of thrust washers ⑤ has been matched and screwed on the handle with bolt ①. When assembling, please make sure not to install the wrong quantity gaskets ⑤, The rubber column ④ is recommended to be replaced every two years (If the handle bar vibration becomes large during use, it can be replaced in advance); Bolt tightening torque is 3-4N, the torque should not be too large, otherwise it will affect the vibration of the handle bar .**